

Safety Alert (SA-26/02): Technician Injured Knee

Incident Description

- The injured person (IP) tripped over a pre-installed bracket used to support welfare unit installation.
- The IP then fell and twisted his knee.

How it Happened

- The welfare unit was positioned horizontally instead of vertically.
- The welfare unit was not placed within the brackets as specified in the work instructions.
- This incorrect positioning created a trip hazard for technicians working in the area.

Key Learnings

- It is important to follow approved safe systems of work and to report any observations.
- Any proposed changes to a safe system of work must be assessed and go through the review and approval process before implementation.